Windows 10 re-install guide

Please note: ensure more than 20% of battery before update.

1,Format the USB-disk of NTFS , and rename to WINPE.

2, Copy all contents in the extracted P2-p2max-os-rs6 - ***** folder to the root directory of the U disk.

3, Insert the USB-disk, turn on the device at the same time press Fn+F7 buttons until the following interface: (Note: press FN + F12 for pocket 2 and pocket 2S)

4, Use the direction keys to select boot items, select the UEFI:XXXX, Partition 1 then press enter key.

5, The following image is an automatic installation system interface. All operation is completed automatically. It will takes about 15 minutes or so. The upgrade will be restarted automatically.

6, After the first start, you will be prompted to select the language and other operations. Notice that you can skip when you connect to the WIFI.